

Appendix D – Transport Drawings & Layouts

D.1 North Wiltshire


D.1.1 Parkgate Farm, Purton (Site Ref N1) Site Assessment



D.1.2 Purton Brickworks Employment Allocation, Purton (Site Ref N2)




D.1.3 Hill Resource Recovery Centre, Compton Bassett (Site Ref N3)




D.1.4 Land East of HRC/WTS at Stanton St Quintin (Site Ref N4)


Access Diagram


File: P:\GBBMA\TP\HB\PROJECTS\Swindon and Wiltshire Waste Sites\070 - CAD\Access Diagrams.dwg






D.1.5 Land West of HRC & WTS, Stanton St Quinton (Site Ref N5) Acess Diagram Site Assessment $\label{eq:File: P:GBBMA TP HB PROJECTS Swindon and Wiltshire Waste Sites 070 - CAD Access Diagrams.dwg$







D.1.6 Land North East of J17 M4, Stanton St Quinton (Site Ref N6) Site Assessment




D.1.7 Park Grounds Farm, Wooton Bassett (Site Ref N7)



D.1.8 Studley Grange Waste Management Facility, Wootton Bassett (Site Ref N8) Site Assessment




D.1.9 Barngrounds, South Cerney (Site Ref N9) Site Assessment





D.1.10 Whitehills Industrial Estate, Wootton Bassett (Site Ref N10)

Site Assessment




D.1.11 Bumpers Farm Industrial Estate (Site Ref N11) Accessibility Map Site Assessment






D.1.12 Thingley Junction, Chippenham (Site Ref N12)

Site Assessment



D.1.13 Leafield industrial Estate, Corsham (Site Ref N13)

Site Assessment



D.1.14 Porte Marsh Industrial Estate, Calne (Site Ref N14) Accessibility Map Site Assessment

