

Ludgershall 24th to 29th May

Before:



After:

Moss and weeds removed from wall line.



Before:



After:

Detritus removed from bus shelter.



Before:



Before:

Bus shelter washed down.



Before:



After:

Weeds and Detritus removed.



Before:



After:

Weeds removed.



Before:



After:

Weeds removed.



Before:



After:

Leaf debris removed.



Before:



After:

Weeds and Detritus removed.

