

R-W-B 10th to 14th June

Before:



After:

Growth removed from around tree.



Before:



After:

Weeds removed from tree base.



Before:



After:

Weeds and Detritus removed from Wall line.



Before:



After:

Back edge of footway cleared of weeds and detritus.



Before:



After:

Weeds and Detritus removed from wall line.



Before:



After:

Wall line cleared of detritus.



Before:



After:

Growth removed from around tree.



Before:



After:

Weeds and detritus removed.



