

Westbury 1st to 4th July

Before:



After:

Footpath cleared back.



Before:



After:

Hedge cut back to give more room on footway.



Before:



After:

Vegetation cut back from footpath.



Before:



After:

Weeds and detritus removed from wall lines.



Before:



After:

Overgrowth cut back from footpath.



Before:



After:

Overgrowth cut back off of footway.



Before:



After:

Hedge cut back from footway.

