

Bradford on Avon 8th to the 11th July

Before:



After:

Roots and debris removed from planters, and topped up with new top soil.



Before:



After:

Weeds removed from wall line.



Before:



After:

Weeds removed from footway.



Before:



After:

Weeds removed from back edge of the footway.



Before:



After:

Weeds removed from back edge of the footway.



Before:



After:

Graffiti removed from bus shelter.



Before:



After:

Weeds and detritus removed from kerb line and back edge of footway.



Before:



After:

Weeds removed from footway.



Before:



After: Detritus removed from back edge of the footway.



