

Amesbury 8th to the 11th July

Before:



After:

Hedge cut back to open up footway.



Before:



After:

Overhanging vegetation cut back from footway.



Before:



After:

Hedge cut back to open up footway.



Before:



After:

Overgrowth cut back from edge of footway.



Before:



After:

Weeds and detritus removed from footway.



Before:



After:

Weeds and cigarette ends removed from footway and kerb line.



Before:



After:

Weeds and detritus removed from wall line.



Before:



After:

Weeds and detritus removed from footway.



Before:



After:

Weeds removed from footway.

