

Calne 15th to 18th July

Before:



After:

Footway cleared of vegetation.



Before:



After:

Weeds removed from wall line.



Before:



After:

Weeds and detritus removed from wall line.



Before:



After:

Weeds and detritus removed.



Before:



After:

Footway cleared of weeds and detritus.



Before:



After:

Weeds removed from block paving.



Before:



After:

Overhanging vegetation cut back from footway.



Before:



After:

Weeds removed from kerb line.



Before:



After:

Weeds and detritus removed from footway.



Before:



After:

Detritus removed from footway.

