

Ludgershall 5th to 8th August

Before:



After:

Shrubs cut back to open up back edge of footway.



Before:



After:

Shrubs cut back and detritus cleared from kerb line.



Before:



After:

Detritus removed from footway.



Before:



After:

Vegetation cut down along fence and wall lines.



Before:



After:

Weeds and detritus removed from kerb line.



Before:



After:

Grass and weeds removed from back edge of footway.



Before:



After:

Back edges of footway Strimmed off.



Before:



After:

Over hanging vegetation cut back to open up footway.



Before:



After:

Low and over hanging branches lifted over footway.



