

Marlborough 12th to 15th August

Before:



After:

Detritus removed from footway.



Before:



After:

Weeds and detritus removed from wall line.



Before:



After:

Over growth cut back to open up footway.



Before:



After:

Overgrowth cut back off fence line.



Before:



After:

Shrub cut back to expose sign.



Before:



After:

Detritus removed from footway, and over hanging hedge cut back.



Before:



After:

Bins washed down.



Before:



After:

Bins washed down.



Before:



After:

Weeds removed from kerb line:



Before:



After:

Footway cleared of detritus and over hanging growth.



