

Tidworth 27th to 30th August

Before:



After:

Hedge trimmed back.



Before:



After:

Sign cleaned.



Before:



After:

Sign cleaned.



Before:



After:

Grass verge Strimmed.



Before:



After:

Grass verge Strimmed.



Before:



After:

Grass Strimmed around bench.



Before:



After:

Footway cleared of detritus.



Before:



After:

Grass verge Strimmed.



