

Warminster 2nd to 5th September

Before:



After:

Shrub cut back from footway.



Before:



After:

Footway cleared of detritus.



Before:



After:

Vegetation cut back from parking area, and detritus removed.



Before:



After:

Bramble removed from hard standing.



Before:



After:

Shrubs cut back to kerb line.



Before:



After:

Shrub cut back to kerb and detritus removed.



Before:



After:

Detritus removed from kerb line and wall line.



Before:



After:

Detritus removed from parking area.

